

1/17




FIG. 1
(PRIOR ART)

2/17




FIG. 2

3/17




FIG. 3

4/17




FIG. 4

5/17





FIG. 5

6/17



7/17

FARO SOFTCHECK TOOL MANAGER

Not Logged In

LOG OFF

1st Time Operator

View Training Video

Operator: User 123

TOOL LIST

REPORTS

START OVER

ENTER PASSWORD ⇄ CONFIRM PASSWORD

▶	*	*	*	*	1	2	3	4	5	6	7	8	9	0
Q	W	E	R	T	Y	U	I	O	P	⇄				
A	S	D	F	G	H	J	K	L	:	"				
Z	X	C	V	B	N	M	,	.	/	?				
SHIFT		SPACE								ENTER				

⇄

FIG. 7

8/17




FIG. 8

9/17

FARO

SOFTCHECK TOOL MANAGER

LOG OFF

Logged In As:

User 123

REPORTS

ADMINISTRATION

START OVER

◀

▶

Tool List

PICTURES

NAME








Part Name	Revision	Date
 FARO Demo Part	3.12 mm	05/17/2000
 Main Gear Strut	757-300	11/11/1986
 Window Belt	14A294	09/21/1998
 Fender	A-27	05/17/2000
		
		
		

FIG. 9

10/17




FIG. 10

11/17




FIG. 11

12/17




FIG. 12

13/17

FARO SOFTCHECK TOOL MANAGER

LOG OFF

Logged In As:
User 123

TOOL LIST

REPORTS

START OVER

Report Preview



Part Name: Fender
Revision: A-27 Date: 05/17/2000

SPC Report - Trends: Over Several Parts



Sample: Last 5 Days (OPTIONS)
Displayed By: Serial Number
Operator: All Operators
Shift: All Shifts

Table Report - Individual Part Information



Last Part:	4927A5
Time/Date:	22:24 - 4/12/2000
Status:	1 Feature out of Tolerance

FIG. 13

14/17




FIG. 14

15/17




FIG. 15

16/17




FIG. 16

17/17




FIG. 17